

## Type NM Cable Strippers/Cutters

Removes Outer Jacket in Seconds

- Finally, a fast and easy way to cut and strip Romex® Cable.
- Cleanly removes the outer jacket of Type NM-B nonmetallic-sheathed cable.
- Quickly strips, cuts and loops conductor wires.
- Saves time, saves money, and helps ensure a quality installation.
- One tool for each cable size does it all!




**KLEIN TOOLS**  
For Professionals... Since 1857™


**Quickly removes outer jacket of Romex® Cable**

Save time, save money and best of all, be sure of a quality installation with Klein's #1012 or #1014 Type NM Cable Strippers/Cutters. In just a matter of seconds, you now can easily remove the outer jacket of Romex® Cable with one tool. These versatile tools also strip, cut and loop the inner conductor wires.

**Features**



**Application Removes Outer Cable Jacket in Seconds**



1. Simply place the cable in the stripping slot. Firmly squeeze the handles fully closed, then release.
2. Holding the cable firmly, quickly bend the cable from side to side, breaking the seal of the outer jacket.
3. Pull or slide off the outer jacket.

**▲WARNING:**

- Always wear approved eye protection.
- Never use on or near live electrical circuits.
- NOT insulated. Plastic-dipped or slip-on plastic handles are NOT intended for protection against electrical shock.

**Ordering Information**

Cat. No.	Type NM-B Cable	AWG Solid Wire Gauges	Handle Color	Length
1012	12/2	No. 12	Yellow with 12/2 at tip	6-1/4" (159 mm)
1014	14/2	No. 14	Yellow with 14/2 at tip	6-1/4" (159 mm)

Romex® is a Registered Trademark of General Cable Industries Inc., or an affiliate.

Supplement A to Catalog 139.1  
© Klein Tools, Inc. 1998  
Printed in U.S.A



**KLEIN TOOLS, INC.**  
7200 McCormick Blvd.  
P.O. Box 599033  
Chicago, IL 60659-9033  
[www.Klein-Tools.com](http://www.Klein-Tools.com)